

Sewer Scope Report

John Doe
123 Main Street,
Somewhere, IL 60000

2/14/2026



Precision Inspection Group

21463 Carlton St,
Crest Hill, IL, 60403

708.969.6017


office@inspectionswithprecision.com

Inspectionswithprecision.com

Inspector: Larry Booth

The purpose of this service is to perform a video camera inspection of the main sewer line only. No other sewer or drain lines were inspected, and all other areas are expressly excluded. The sewer line is accessed through a single, readily accessible access point located within the main structure or on the exterior of the property.

The objective of this inspection is to evaluate the main sewer line for visible obstructions, damage, or adverse conditions and to document any observed concerns. This service does not include inspection of all drain lines within the property. The distance of the inspection may be limited by obstructions, pipe conditions, or friction within the sewer line.



Sewer Scope Inspection

1. Location

Exterior

2. Pipe material

Cast iron

3. Length

Total 53 feet

4. Findings

No issues observed

Observations:

- [Click Here for Video](#)

5. Conclusion

Observations:

- No issues or defects were observed in the sanitary piping during the inspection.