

Chimney Flue Scan Report

John Doe
123 Main Street,
Somewhere, 60000
2/14/2026



Precision Inspection Group

21463 Carlton St,
Crest Hill, IL 60403
708.969.6017


office@inspectionswithprecision.com
Inspectionswithprecision.com

Inspector: Larry Booth

Chimney Flue Scan – Purpose and Scope

A chimney flue scan is conducted to evaluate the interior condition, safety, and structural integrity of the chimney flue, which serves as the passage for smoke, combustion gases, and other byproducts to exit the home. Using specialized video camera equipment, this inspection enables a detailed visual assessment of areas that are not accessible or visible through standard exterior observation, helping to identify concealed damage, deterioration, blockages, or other conditions that may impact performance or safety.

The scope of this service is strictly limited to a video camera inspection of the chimney flue only. No other chimney components or building systems were inspected, and all areas outside the flue are expressly excluded and disclaimed. The purpose of this inspection is to document the flue's observable condition and to identify, based on the inspector's professional judgment, any conditions that may warrant repair, maintenance, cleaning, or further evaluation.



Chimney Flue Scan Inspection

1. Location of fireplace

Living room

2. Type of flue

Metal

3. Findings

No issues found

Observations:

- [Click Here for Video](#)

4. Conclusion

Observations:

- No issues or problems were observed in the fireplace flue(s).